

CHIEF XD™ FOG NOZZLE

PRODUCT AWARENESS BULLETIN

July 2024

THE ISSUE

There have been an isolated number of occurrences where stream quality has been inconsistent in the straight stream position.

PRODUCTS AFFECTED

Chief XD Models: 160 GPM @ 50 psi & 175 GPM @ 50 psi, One-Piece Nozzles and Tips

HOW TO TELL IF MY NOZZLE IS AFFECTED

Indicators

- Upon shutting (either fully or partially) and opening bale, stream quality is poor and does not always self-correct/cleanup or takes several seconds to adjust.
- Adjusting the tip slightly results in stream improvement and correction.

If this condition exists, it should be noticeable on your normal operational equipment testing and inspection.



WHAT TO DO IF MY NOZZLE IS AFFECTED

Contact Elkhart Brass Customer Service for immediate repair.

Phone:
800-346-0250
574-295-8330

Email:
eb.info@safefleet.net

Website:
www.elkhartbrass.com